

SK20010FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	15.6	100	57.8
F	0.2	1.5	0.85
Cl	7.8	100	53.9
SO₄	94.2	250	172.1
Fe	0.04	0.2	0.12
Mn	0.07	0.05	0.07
NH₄	0.05	0.5	0.275
Cr	0.002	0.05	0.026
Cu	0.007	1	0.5035
As	0.002	0.01	0.006
Cd	0.002	0.003	0.0025
Se	0.001	0.01	0.0055
Pb	0.008	0.01	0.009
Hg	0.0004	0.001	0.0007

SK2000200P

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	58.1	100	79.05
F	0.3	1.5	0.9
Cl	70.3	100	85.15
SO₄	183	250	216.5
Fe	0.05	0.2	0.125
Mn	0.03	0.05	0.04
NH₄	0.05	0.5	0.275
Cr	0.001	0.05	0.0255
Cu	0.004	1	0.502
As	0.001	0.01	0.0055
Cd	0.00005	0.003	0.001525
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0003	0.001	0.00065

SK200030FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	7.5	100	53.75
F	0.2	1.5	0.85
Cl	9.2	100	54.6
SO₄	86.8	250	168.4
Fe	0.05	0.2	0.125
Mn	0.01	0.05	0.03
NH₄	0.03	0.5	0.265
Cr	0.001	0.05	0.0255
Cu	0.001	1	0.5005
As	0.0005	0.01	0.00525
Cd	0.0005	0.003	0.00175
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0002	0.001	0.0006

SK2000400P

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	12.3	100	56.15
F	0.02	1.5	0.76
Cl	7.1	100	53.55
SO₄	27.2	250	138.6
Fe	0.05	0.2	0.125
Mn	0.01	0.05	0.03
NH₄	0.02	0.5	0.26
Cr	0.002	0.05	0.026
Cu	0.002	1	0.501
As	0.002	0.01	0.006
Cd	0.002	0.003	0.0025
Se	0.001	0.01	0.0055
Pb	0.004	0.01	0.007
Hg	0.0004	0.001	0.0007

SK2000500P

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	8.5	100	54.25
F	0.2	1.5	0.85
Cl	20.3	100	60.15
SO₄	42.2	250	146.1
Fe	0.03	0.2	0.115
Mn	0.01	0.05	0.03
NH₄	0.03	0.5	0.265
Cr	0.002	0.05	0.026
Cu	0.005	1	0.5025
As	0.001	0.01	0.0055
Cd	0.001	0.003	0.002
Se	0.001	0.01	0.0055
Pb	0.004	0.01	0.007
Hg	0.0001	0.001	0.00055

SK200060KF

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	4.4	100	52.2
F	0.2	1.5	0.85
Cl	9.4	100	54.7
SO₄	42	250	146
Fe	0.05	0.2	0.125
Mn	0.003	0.05	0.0265
NH₄	0.05	0.5	0.275
Cr	0.001	0.05	0.0255
Cu	0.001	1	0.5005
As	0.0005	0.01	0.00525
Cd	0.00005	0.003	0.001525
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0001	0.001	0.00055

SK2000700F

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	2.7	100	51.35
F	0.05	1.5	0.775
Cl	5.3	100	52.65
SO₄	32.6	250	141.3
Fe	0.03	0.2	0.115
Mn	0.006	0.05	0.028
NH₄	0.04	0.5	0.27
Cr	0.002	0.05	0.026
Cu	0.005	1	0.5025
As	0.001	0.01	0.0055
Cd	0.001	0.003	0.002
Se	0.001	0.01	0.0055
Pb	0.004	0.01	0.007
Hg	0.0001	0.001	0.00055

SK200080KF

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	17.2	100	58.6
F	0.2	1.5	0.85
Cl	5.7	100	52.85
SO₄	64.2	250	157.1
Fe	0.05	0.2	0.125
Mn	0.003	0.05	0.0265
NH₄	0.05	0.5	0.275
Cr	0.001	0.05	0.0255
Cu	0.001	1	0.5005
As	0.0005	0.01	0.00525
Cd	0.00005	0.003	0.001525
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0002	0.001	0.0006

SK200090FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	8.3	100	54.15
F	0.07	1.5	0.785
Cl	6.3	100	53.15
SO₄	30.6	250	140.3
Fe	0.02	0.2	0.11
Mn	0.005	0.05	0.0275
NH₄	0.04	0.5	0.27
Cr	0.002	0.05	0.026
Cu	0.003	1	0.5015
As	0.001	0.01	0.0055
Cd	0.0005	0.003	0.00175
Se	0.001	0.01	0.0055
Pb	0.004	0.01	0.007
Hg	0.0001	0.001	0.00055
Al		0.2	0.1

SK2001000P

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	56	100	78
F		1.5	0.75
Cl	104	100	102
SO₄	79	250	164.5
Fe	0.03	0.2	0.115
Mn	0.003	0.05	0.0265
NH₄	0.06	0.5	0.28
Cr	0.002	0.05	0.026
Cu	0.002	1	0.501
As	0.001	0.01	0.0055
Cd	0.0005	0.003	0.00175
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0001	0.001	0.00055
Al		0.2	0.1

SK200110FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	11	100	55.5
F	0.1	1.5	0.8
Cl	6.3	100	53.15
SO₄	14	250	132
Fe	0.04	0.2	0.12
Mn	0.007	0.05	0.0285
NH₄	0.03	0.5	0.265
Cr	0.002	0.05	0.026
Cu	0.005	1	0.5025
As	0.002	0.01	0.006
Cd	0.001	0.003	0.002
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0001	0.001	0.00055
Al		0.2	0.1

SK200120FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	14.1	100	57.05
F	0.4	1.5	0.95
Cl	6.4	100	53.2
SO₄	56.1	250	153.05
Fe	0.05	0.2	0.125
Mn	0.04	0.05	0.045
NH₄	0.06	0.5	0.28
Cr	0.002	0.05	0.026
Cu	0.002	1	0.501
As	0.0005	0.01	0.00525
Cd	0.0002	0.003	0.0016
Se	0.001	0.01	0.0055
Pb	0.004	0.01	0.007
Hg	0.0001	0.001	0.00055
Al		0.2	0.1

SK2001300P

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	5.2	100	52.6
F	0.3	1.5	0.9
Cl	2.5	100	51.25
SO₄	31.6	250	140.8
Fe	0.05	0.2	0.125
Mn	0.01	0.05	0.03
NH₄	0.03	0.5	0.265
Cr	0.001	0.05	0.0255
Cu	0.001	1	0.5005
As	0.001	0.01	0.0055
Cd	0.00005	0.003	0.001525
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0001	0.001	0.00055

SK200140KF

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	3.8	100	51.9
F	0.08	1.5	0.79
Cl	9.7	100	54.85
SO₄	28.3	250	139.15
Fe	0.06	0.2	0.13
Mn	0.005	0.05	0.0275
NH₄	0.07	0.5	0.285
Cr	0.002	0.05	0.026
Cu	0.003	1	0.5015
As	0.0005	0.01	0.00525
Cd	0.0003	0.003	0.00165
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.00005	0.001	0.000525

SK200150FP

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	20.4	100	60.2
F	0.2	1.5	0.85
Cl	15.2	100	57.6
SO₄	36.2	250	143.1
Fe	0.02	0.2	0.11
Mn	0.01	0.05	0.03
NH₄	0.2	0.5	0.35
Cr	0.002	0.05	0.026
Cu	0.002	1	0.501
As	0.002	0.01	0.006
Cd	0.0005	0.003	0.00175
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.00005	0.001	0.000525

SK200160FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	8	100	54
F	0.1	1.5	0.8
Cl	2.1	100	51.05
SO₄	36	250	143
Fe	0.07	0.2	0.135
Mn	0.008	0.05	0.029
NH₄	0.06	0.5	0.28
Cr	0.001	0.05	0.0255
Cu	0.002	1	0.501
As	0.002	0.01	0.006
Cd	0.0006	0.003	0.0018
Se	0.001	0.01	0.0055
Pb	0.004	0.01	0.007
Hg	0.0001	0.001	0.00055

SK200170FP

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	4.2	100	52.1
F	0.07	1.5	0.785
Cl	9.4	100	54.7
SO₄	44.5	250	147.25
Fe	0.07	0.2	0.135
Mn	0.009	0.05	0.0295
NH₄	0.06	0.5	0.28
Cr	0.002	0.05	0.026
Cu	0.004	1	0.502
As	0.002	0.01	0.006
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.00005	0.001	0.000525

SK2001800F

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	3.5	100	51.75
F	0.1	1.5	0.8
Cl	3.7	100	51.85
SO₄	64.3	250	157.15
Fe	0.05	0.2	0.125
Mn	0.003	0.05	0.0265
NH₄	0.02	0.5	0.26
Cr	0.001	0.05	0.0255
Cu	0.001	1	0.5005
As	0.0005	0.01	0.00525
Cd	0.00005	0.003	0.001525
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0002	0.001	0.0006

SK200190FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	7.5	100	53.75
F	0.1	1.5	0.8
Cl	16.3	100	58.15
SO₄	89.3	250	169.65
Fe	0.01	0.2	0.105
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.001	0.05	0.0255
Cu	0.001	1	0.5005
As	0.0005	0.01	0.00525
Cd	0.00005	0.003	0.001525
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0001	0.001	0.00055

SK200340KF

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	4.6	100	52.3
F	0.1	1.5	0.8
Cl	2.8	100	51.4
SO₄	35.9	250	142.95
Fe	0.01	0.2	0.105
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.001	0.05	0.0255
Cu	0.001	1	0.5005
As	0.001	0.01	0.0055
Cd	0.0005	0.003	0.00175
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK200350FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	1.8	100	50.9
F	0.1	1.5	0.8
Cl	1.8	100	50.9
SO₄	9.5	250	129.75
Fe	0.01	0.2	0.105
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.001	0.05	0.0255
Cu	0.001	1	0.5005
As	0.001	0.01	0.0055
Cd	0.0005	0.003	0.00175
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK2003200P

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	6.4	100	53.2
F	0.2	1.5	0.85
Cl	16.2	100	58.1
SO₄	46.6	250	148.3
Fe	0.07	0.2	0.135
Mn	0.2	0.05	0.2
NH₄	0.03	0.5	0.265
Cr	0.001	0.05	0.0255
Cu	0.001	1	0.5005
As	0.005	0.01	0.0075
Cd	0.0005	0.003	0.00175
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK2003300F

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	21.8	100	60.9
F	0.2	1.5	0.85
Cl	40.1	100	70.05
SO₄	168.4	250	209.2
Fe	0.01	0.2	0.105
Mn	0.01	0.05	0.03
NH₄	0.05	0.5	0.275
Cr	0.0005	0.05	0.02525
Cu	0.002	1	0.501
As	0.005	0.01	0.0075
Cd	0.0005	0.003	0.00175
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK200300FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	2.3	100	51.15
F	0.1	1.5	0.8
Cl	2.3	100	51.15
SO₄	54.6	250	152.3
Fe	0.01	0.2	0.105
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.002	0.05	0.026
Cu	0.001	1	0.5005
As	0.001	0.01	0.0055
Cd	0.001	0.003	0.002
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK2003100P

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	3.7	100	51.85
F	0.3	1.5	0.9
Cl	5.4	100	52.7
SO₄	40.7	250	145.35
Fe	0.01	0.2	0.105
Mn	0.01	0.05	0.03
NH₄	0.03	0.5	0.265
Cr	0.001	0.05	0.0255
Cu	0.001	1	0.5005
As	0.001	0.01	0.0055
Cd	0.0005	0.003	0.00175
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0001	0.001	0.00055

SK200280FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	7.4	100	53.7
F	0.1	1.5	0.8
Cl	5.9	100	52.95
SO₄	35.5	250	142.75
Fe	0.02	0.2	0.11
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.002	0.05	0.026
Cu	0.001	1	0.5005
As	0.001	0.01	0.0055
Cd	0.001	0.003	0.002
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK200290FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	3.4	100	51.7
F	0.1	1.5	0.8
Cl	3.2	100	51.6
SO₄	22.5	250	136.25
Fe	0.02	0.2	0.11
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.002	0.05	0.026
Cu	0.001	1	0.5005
As	0.01	0.01	0.01
Cd	0.0005	0.003	0.00175
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK200260FP

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	16.1	100	58.05
F	0.2	1.5	0.85
Cl	20.6	100	60.3
SO₄	53.2	250	151.6
Fe	0.02	0.2	0.11
Mn	0.01	0.05	0.03
NH₄	0.05	0.5	0.275
Cr	0.001	0.05	0.0255
Cu	0.001	1	0.5005
As	0.001	0.01	0.0055
Cd	0.0005	0.003	0.00175
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0001	0.001	0.00055

SK200270KF

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	2.3	100	51.15
F	0.1	1.5	0.8
Cl	2.8	100	51.4
SO₄	41.2	250	145.6
Fe	0.04	0.2	0.12
Mn	0.01	0.05	0.03
NH₄	0.05	0.5	0.275
Cr	0.001	0.05	0.0255
Cu	0.001	1	0.5005
As	0.001	0.01	0.0055
Cd	0.0005	0.003	0.00175
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0001	0.001	0.00055

SK200240FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	4.9	100	52.45
F	0.1	1.5	0.8
Cl	2.7	100	51.35
SO₄	32.1	250	141.05
Fe	0.01	0.2	0.105
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.0005	0.05	0.02525
Cu	0.001	1	0.5005
As	0.001	0.01	0.0055
Cd	0.0005	0.003	0.00175
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0002	0.001	0.0006

SK200250KF

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	1.9	100	50.95
F	0.1	1.5	0.8
Cl	3	100	51.5
SO₄	30.8	250	140.4
Fe	0.02	0.2	0.11
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.0005	0.05	0.02525
Cu	0.003	1	0.5015
As	0.001	0.01	0.0055
Cd	0.0005	0.003	0.00175
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0002	0.001	0.0006

SK200220FP

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	12.1	100	56.05
F	0.1	1.5	0.8
Cl	5.1	100	52.55
SO₄	42.7	250	146.35
Fe	0.02	0.2	0.11
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.0004	0.05	0.0252
Cu	0.002	1	0.501
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK2002300P

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	53	100	76.5
F	0.3	1.5	0.9
Cl	46.3	100	73.15
SO₄	66.8	250	158.4
Fe	0.02	0.2	0.11
Mn	0.01	0.05	0.03
NH₄	0.03	0.5	0.265
Cr	0.002	0.05	0.026
Cu	0.002	1	0.501
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.002	0.01	0.006
Pb	0.001	0.01	0.0055
Hg	0.00001	0.001	0.000505

SK200200FP

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	6.5	100	53.25
F	0.1	1.5	0.8
Cl	2.3	100	51.15
SO₄	37.2	250	143.6
Fe	0.01	0.2	0.105
Mn	0.003	0.05	0.0265
NH₄	0.02	0.5	0.26
Cr	0.001	0.05	0.0255
Cu	0.001	1	0.5005
As	0.0005	0.01	0.00525
Cd	0.00005	0.003	0.001525
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0002	0.001	0.0006

SK2002100P

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	10	100	55
F	0.1	1.5	0.8
Cl	6.4	100	53.2
SO₄	50.3	250	150.15
Fe	0.01	0.2	0.105
Mn	0.01	0.05	0.03
NH₄	0.02	0.5	0.26
Cr	0.001	0.05	0.0255
Cu	0.001	1	0.5005
As	0.0005	0.01	0.00525
Cd	0.00005	0.003	0.001525
Se	0.002	0.01	0.006
Pb	0.002	0.01	0.006
Hg	0.0001	0.001	0.00055

SK200430FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	5.7	100	52.85
F	0.1	1.5	0.8
Cl	5.8	100	52.9
SO₄	44.1	250	147.05
Fe	0.04	0.2	0.12
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.0013	0.05	0.02565
Cu	0.0018	1	0.5009
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK200440KF

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	0.9	100	50.45
F	0.1	1.5	0.8
Cl	1.4	100	50.7
SO₄	26.9	250	138.45
Fe	0.01	0.2	0.105
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.001	0.05	0.0255
Cu	0.0004	1	0.5002
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK2004500P

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	10.3	100	55.15
F	0.3	1.5	0.9
Cl	10	100	55
SO₄	52.5	250	151.25
Fe	0.01	0.2	0.105
Mn	0.079	0.05	0.0645
NH₄	0.03	0.5	0.265
Cr	0.0008	0.05	0.0254
Cu	0.001	1	0.5005
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0001	0.001	0.00055

SK200460KF

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	2.5	100	51.25
F	0.1	1.5	0.8
Cl	5	100	52.5
SO₄	54.2	250	152.1
Fe	0.01	0.2	0.105
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.0004	0.05	0.0252
Cu	0.0013	1	0.50065
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK2004700P

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	7.5	100	53.75
F	0.1	1.5	0.8
Cl	5.8	100	52.9
SO₄	61.6	250	155.8
Fe	0.02	0.2	0.11
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.0004	0.05	0.0252
Cu	0.0013	1	0.50065
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0001	0.001	0.00055

SK200480KF

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	4.6	100	52.3
F	0.1	1.5	0.8
Cl	13.5	100	56.75
SO₄	85.1	250	167.55
Fe	0.01	0.2	0.105
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.0004	0.05	0.0252
Cu	0.001	1	0.5005
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK2004900F

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	6.5	100	53.25
F	0.2	1.5	0.85
Cl	3.3	100	51.65
SO₄	84	250	167
Fe	0.01	0.2	0.105
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.0004	0.05	0.0252
Cu	0.001	1	0.5005
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK200500FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	5.2	100	52.6
F	0.1	1.5	0.8
Cl	4.8	100	52.4
SO₄	39.3	250	144.65
Fe	0.02	0.2	0.11
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.0004	0.05	0.0252
Cu	0.001	1	0.5005
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK200510KF

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	7.7	100	53.85
F	0.2	1.5	0.85
Cl	8	100	54
SO₄	84.2	250	167.1
Fe	0.01	0.2	0.105
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.0004	0.05	0.0252
Cu	0.0004	1	0.5002
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0001	0.001	0.00055

SK2005200P

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	20.6	100	60.3
F	0.3	1.5	0.9
Cl	52.8	100	76.4
SO₄	69.4	250	159.7
Fe	0.05	0.2	0.125
Mn	0.025	0.05	0.0375
NH₄	0.03	0.5	0.265
Cr	0.001	0.05	0.0255
Cu	0.002	1	0.501
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK2005300P

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	22.1	100	61.05
F	0.1	1.5	0.8
Cl	25.5	100	62.75
SO₄	80.1	250	165.05
Fe	0.05	0.2	0.125
Mn	0.025	0.05	0.0375
NH₄	0.03	0.5	0.265
Cr	0.0004	0.05	0.0252
Cu	0.003	1	0.5015
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK200540FP

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	11	100	55.5
F	0.1	1.5	0.8
Cl	6	100	53
SO₄	63.7	250	156.85
Fe	0.03	0.2	0.115
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.0004	0.05	0.0252
Cu	0.003	1	0.5015
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK200550FP

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	14	100	57
F	0.1	1.5	0.8
Cl	7.3	100	53.65
SO₄	57.9	250	153.95
Fe	0.04	0.2	0.12
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.0004	0.05	0.0252
Cu	0.004	1	0.502
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK200560FK

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	13.9	100	56.95
F	0.1	1.5	0.8
Cl	26.8	100	63.4
SO₄	59.9	250	154.95
Fe	0.01	0.2	0.105
Mn	0.004	0.05	0.027
NH₄	0.03	0.5	0.265
Cr	0.0004	0.05	0.0252
Cu	0.0005	1	0.50025
As	0.001	0.01	0.0055
Cd	0.0003	0.003	0.00165
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK2005700F

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	14.6	100	57.3
F	0.1	1.5	0.8
Cl	11.7	100	55.85
SO₄	47.2	250	148.6
Fe	0.01	0.2	0.105
Mn	0.01	0.05	0.03
NH₄	0.03	0.5	0.265
Cr	0.0004	0.05	0.0252
Cu	0.002	1	0.501
As	0.001	0.01	0.0055
Cd	0.0004	0.003	0.0017
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK2005800P

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	27.5	100	63.75
F	0.2	1.5	0.85
Cl	52.7	100	76.35
SO₄	85.6	250	167.8
Fe	0.01	0.2	0.105
Mn	0.02	0.05	0.035
NH₄	0.03	0.5	0.265
Cr	0.0003	0.05	0.02515
Cu	0.001	1	0.5005
As	0.001	0.01	0.0055
Cd	0.0003	0.003	0.00165
Se	0.001	0.01	0.0055
Pb	0.001	0.01	0.0055
Hg	0.0001	0.001	0.00055

SK200590FP

Zložka	Požadovaná hodnota	Referenčná hodnota	Prahová hodnota
Na	4.3	100	52.15
F	0.1	1.5	0.8
Cl	3.2	100	51.6
SO₄	23.9	250	136.95
Fe	0.04	0.2	0.12
Mn	0.003	0.05	0.0265
NH₄	0.03	0.5	0.265
Cr	0.0008	0.05	0.0254
Cu	0.0014	1	0.5007
As	0.0008	0.01	0.0054
Cd	0.0014	0.003	0.0022
Se	0.001	0.01	0.0055
Pb	0.002	0.01	0.006
Hg	0.0001	0.001	0.00055